

SHEILA JACKSON LEE
18TH DISTRICT, TEXAS

WASHINGTON OFFICE:
2160 Rayburn House Office Building
Washington, DC 20515
(202) 225-3816

DISTRICT OFFICE:
1919 SMITH STREET, SUITE 1180
THE GEORGE "MICKEY" LELAND FEDERAL BUILDING
HOUSTON, TX 77002
(713) 655-0050

ACRES HOME OFFICE:
6719 WEST MONTGOMERY, SUITE 204
HOUSTON, TX 77019
(713) 691-4882

HEIGHTS OFFICE:
420 WEST 19TH STREET
HOUSTON, TX 77008
(713) 961-4070

FIFTH WARD OFFICE:
4300 LYONS AVENUE, SUITE 200
HOUSTON, TX 77020
(713) 227-7740

Congress of the United States
House of Representatives
Washington, DC 20515

COMMITTEES:
JUDICIARY
SUBCOMMITTEES:
COURTS, INTELLECTUAL PROPERTY AND THE INTERNET
IMMIGRATION AND BORDER SECURITY
HOMELAND SECURITY
SUBCOMMITTEES:
RANKING MEMBER
BORDER AND MARITIME SECURITY
TRANSPORTATION SECURITY
SENIOR WHIP
DEMOCRATIC CAUCUS

April 29, 2022

The Honorable Rosa DeLauro
Chair
U.S. House Committee on Appropriations
H-307 The Capitol
Washington, DC 20515

The Honorable Kay Granger
Ranking Member
U.S. House Committee on Appropriations
1036 Longworth House Office Building
Washington, DC 20515

Dear Chair DeLauro and Ranking Member Granger,

I am submitting a programmatic funding request on behalf of Houston's District B's Flood prevention project for fiscal year 2023 to the Subcommittee on Energy and Water in the amount of \$6,606,800.00.

This funding Upsize storm sewer based on drainage study. Includes hydraulic & hydrologic analysis of the system to determine storm sewer system improvements needed to alleviate flooding/severe ponding. Clearing and Grubbing of ditch and re-establish proper grade. Hydraulic & Hydrologic analysis to recommend upsizing the existing storm system to achieve 2-yr LOS. Clearing and Grubbing of ditch and re-establish proper grade. Recommend Hydraulic & Hydrologic analysis to determine proposed improvements within the neighborhood. Hydraulic & Hydrologic analysis to determine proposed improvements within the neighborhood. Clearing and Grubbing of ditch and re-establish proper grade. Re-establish proper grade (de-silt). Replace culverts (i.e. undersized, collapsed) not set to proper flow line. Re-establish proper grade (de-silt) of the ditch. Replace culverts (i.e. undersized, collapsed) not set to proper flow line. Re-establish proper grade (de-silt). Replace culverts (i.e. undersized, collapsed) not set to proper flow line. Re-establish proper grade (de-silt). Replace culverts (i.e. undersized, collapsed) not set to proper flow line. Hydraulic & Hydrologic analysis to determine proposed improvements within the neighborhood. Recommend Hydraulic & Hydrologic analysis to determine proposed improvements within the neighborhood. Upsize existing storm sewer system based on recommendations from H&H Analyses.

I certify that neither I nor my immediate family has any financial interest in any of these projects.

Very truly yours,



Sheila Jackson Lee
MEMBER OF CONGRESS